

FIG. 1 (PRIOR ART)




FIG. 1 (PRIOR ART)

FIG. 2 (PRIOR ART)




FIG. 2 (PRIOR ART)




FIG. 3 (PRIOR ART)




FIG. 4 (PRIOR ART)




FIG. 5 (PRIOR ART)




FIG. 6




FIG. 7




FIG. 7A




FIG. 8 (PRIOR ART)




FIG. 9



for  $i=0,1,\dots,S-1$




FIG. 10




FIG. 11

input quadrant(s)	rotation operation	output quadrant(s)
0	-64	3
1	-64	0
0 and 1	-64	0 and 3
2	+64	3
1 and 2	+128	0 and 3
3	+64	0
2 and 3	+64	0 and 3
0 and 3	none	0 and 3

Fig. 12




FIG. 13